

SECTION V - HEALTH HAZARD DATA

EFFECTS OF OVEREXPOSURE - Conditions to Avoid Slight eye and skin irritation can result.	THRESHOLD LIMIT VALUE PERMISSIBLE EXPOSURE LIMIT 5.00 mg/m ³
PRIMARY ROUTES OF ENTRY X INHALATION X SKIN CONTACT X EYE CONTACT X INGESTION	
EMERGENCY AND FIRST AID PROCEDURES Skin: Wash with soap and water. Ingestion: Do not induce vomiting call doctor. Eyes: Flush with water Inhalation: Move to fresh air.	

SECTION VI - REACTIVITY DATA

STABILITY	UNSTABLE		
	STABLE	X	
INCOMPATIBILITY (materials to avoid) Avoid contact with strong oxidizing agents			

SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Contain spill, mop or absorb on fire retardant treated sawdust or other absorbent material, eliminate all ignition sources, ventilate area.
WASTE DISPOSAL METHOD Dispose into regulatory disposal facility in accordance with local laws.

SECTION VIII - SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION None, other than adequate ventilation.		
VENTILATION		
	ADEQUATE	
PROTECTIVE GLOVES (Specify type) Avoid Skin Contact - Rubber Gloves	EYE PROTECTION (specify type) Safety Glasses	
OTHER PROTECTIVE EQUIPMENT None Required		

SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING Combustible liquid, keep away from fire, sparks and extreme heat.
--

ADDITIONAL HEALTH DATA COMMENT

The above information is based on the data of which we are aware and is believed to be correct as of the data hereof. Since the information contained herein may be applied under conditions beyond our control and with which we may be unfamiliar and since data made available subsequent to the date hereof may suggest modification of the information, we do not assume any responsibility for the results of its use. This information is furnished upon condition that the person receiving it shall make his own determination of the suitability of the material for his particular purpose.